

Figure 1 is a schematic diagram of a mechanical assembly 1. The assembly consists of a cylindrical member 3 and a wedge-shaped member 2. The cylindrical member 3 has a central hole 5. The wedge-shaped member 2 is positioned to the right of the cylindrical member 3, with its tip pointing towards the center of the hole 5. The assembly is shown in a cross-sectional view. The cylindrical member 3 has a length L1 and a diameter h1. The wedge-shaped member 2 has a length L2 and a height h2. The members are joined at a point A. The diagram shows various surfaces and edges labeled with numbers 1 through 5, and dimensions L1, L2, h1, and h2.

[illegible]

Fig.2





Fig.3



[illegible]